

2001-07 JEEP LIBERTY TRAILER HITCH

		Pa	arts List		TOOLS REQUIRED
ITEM	1 Q	TY PART NUMBER	DESCRIPTION		RATCHET
1	6	6 M12-1.75 x 35mm	HEX TAP BOLT		TORQUE WRENCH
2	1	6 1/2"	CONICAL TOOTHED WASHER	Ţ	19mm or 3/4in SOCKET
			WELDNUT CLEANING To remove debris from weldnuts in frame, spray lubricant or compressed air into hole. For heavy debris, use a small wire brush. (Be careful not to damage threads).	PASSENGER SIDE FRAME RAIL VEHICLE FUELTANK SKID SHIELD	
		2	EXISTING WELDNUT DRIVER SI	SIDE FRAME RAIL	

INSTALLATION INSTRUCTIONS:

- 1) Remove rear tow hook if present, tow hook cannot be used with hitch.
- 2) Support the fuel tank skid shield, then remove the (6) M12 fasteners securing the fuel tank skid shield to the frame rails if equipped, discard fasteners.
- 3) Raise the hitch into position, sandwiching the fuel tank skid shield between the frame and the hitch, loosely install M12 fasteners with 1/2"conical washers.

4)Torque all M12 fasteners to 65 lb-ft (88 N•m).

June 26, 2012 K6861664